

Manhole Inspection Summary

Manhole # S02YY1005MH

Printed On: 12/17/2008

Page 1 of 4

Inspection Is Incomplete Rating: **2) Good**

Record Plat: **02YY1** Node: **005** Status: **Found**

Insp Date: **7/27/06 8:44 AM**

Incomplete Comments

Crew: **CH, IJ**
Inspector: **Hale, C**
Firm: **RKK**

Location Address: **3611 Fords Ln**

Cross Street: **Park Heights Ave**

Manhole Type: **Offset (type 2)**

Location: **Roadway**

Ground Conditions: **Dry**

Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **County Lid**

Cover Shape: **Circular**

Diameter: **24** (in.) Length: (in.) Dist A/B Grade: **0** (in.)

Type: **Other**

Condition: **Sound**

Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **0** (in.)

Condition: Sound Cracked Leaks

Chimney / Frame Adjustment Exists Material: **Brick** Parged Height: **9** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None **Joint** Cracks Mortar Roots Wall

Corbel Material: **Brick**

Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Barrel Material: **Brick**

Parged

Shape: **D-Shape** Diameter: **42** (in.) Length: **42** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Bench Exists Material: **Brick**

Parged Debris (not Condition related)

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Brick**

Parged Debris (not Condition related)

Channel Exposure: **Fully Open** Junc Dist: **2** nearest .5 ft. Azimuth: **30**

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Steps Count: **5** Missing: **0** Corroded

Surcharge Evidence Of Surcharge Depth: (ft.) Active Surcharge Present

Location View



Top View



10 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **8.27** (ft.) Flow Characteristics: **Fast**

Deposits: None Mud Sludge Debris Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

8 in. Circular Gravity Sewer
Pipe In @ 3 O'Clock



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **8.00** (ft.) Flow Characteristics: **Slow**

Deposits: None Mud Sludge Debris Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

Manhole Inspection Summary

Manhole # S02YY1005MH

Printed On: 12/17/2008

Page 4 of 4

10 in. Circular Gravity Sewer

Pipe In @ 6 O'Clock



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **8.22** (ft.) Flow Characteristics: **Fast**

Deposits: None Mud Sludge Debris Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection
